

## Internal notes

Added By

David Brockhouse • 06/16/2021 2:17 PM

### Note

The violations for the first re-inspection V2 were corrected. The inspection of the additional units indicate many other units have not yet had old smoke alarms replaced. All units did have fire extinguishers but they still need to be mounted. In the 10 additional (random) units inspected other violations were found and a re-inspection of these units plus another additional 10 random units will be inspected for the V3 inspection