



NOTICE OF UNSAFE STRUCTURE

ORDER OF EVACUATION

Date: July 3, 2024

Address: 19 S. Sixth St.

Owner: Hathman, Connie Ann Trust and James Scott Hathman Trust

In accordance with the 2018 IBC Section 116, this structure is unsafe due to a partial roof and wall collapse in the northwest corner. The structure is not to be occupied until the building is made structurally sound. A structural engineer shall provide a report and oversee repairs to the structure. The alleyway shall be barricaded until such time as the building is in a structurally sound condition.

Phil Teeple, P.E.

Engineering Manager

Community Development - Building and Site Development